



DEPARTMENT OF THE AIR FORCE
75TH CIVIL ENGINEERING (CEOHA)
HILL AIR FORCE BASE, UTAH



ASBESTOS LEAD BASED PAINT LIMITED INSPECTION REPORT

INSPECTION DATE: 01 June 2022

(This inspection is valid for three years from the inspection date regardless of Exp. Date of inspector cert. If past this date, a visual or additional assessment will then be required)

Reference UDAQ R307-807-6

Utah Certified State Inspector: Kyle Daly

(ASB#-7321: Expires-17 Sept. 2022, PB#-2753: Expires-17 March 2024)

INSTALL NEW CHILLERS

WORK TASK/CAPITAL PROJECT #: 7471995

FACILITY: 118

FACILITY CONSTRUCTION DATE: 1980

REQUESTER: CURTIS WRIGHT

ORGANIZATION: 388 FW

REQUESTED: 05 March 2020



THE QUANTITIES WITHIN THIS REPORT ARE ESTIMATES AND SHOULD
NOT BE USED FOR BIDDING PURPOSES

PREPARED BY: Kyle Daly (ASB#-7321, PB#-2753)

SIGNATURE: _____



DEPARTMENT OF THE AIR FORCE
75 CIVIL ENGINEERING (CEOHA)
HILL AIR FORCE BASE, UTAH



LIMITED ASBESTOS INSPECTION REPORT INFORMATION

Statement of Work: Install new chillers.

This inspection was performed in accordance with the Utah Division of Air Quality (DAQ) requirements as found in the Utah Air Quality Rule R307-801-10. This inspection report is required to be on site during all abatement, renovation, and demolition activities. Samples referenced in this report were analyzed by polarized light microscopy (PLM) utilizing method 600R-93-116 by The Science and Engineering Laboratory (AIHA Acc.#-101572) at Hill Air Force Base, Utah (R307-801-10.8.a-b).

Civil Engineering personnel also reviewed previous asbestos inspection reports of suspect asbestos containing materials (ACM) that could potentially be encountered in the proposed area/areas. The information gathered from all current and previous inspections is shown below by homogenous area (R307-801-9-4).

The quantities within this report are estimates and are not to be used for bidding purposes.

SUMMARY OF ASBESTOS CONTAINING MATERIALS FOUND					
MATERIAL TYPE	ASBESTOS	FRIABILITY	*RACM *Category I *Category II	QUANTITY	*LOCATIONS FOUND
N/A	N/A	N/A	N/A	N/A	N/A

Table 1

***Per UDAQ definition.**

RACM: Regulated Asbestos-Containing Material (RACM)" means friable ACM, Category I non-friable ACM that has become friable, Category I non-friable ACM that will be or has been subjected to sanding, grinding, cutting, or abrading, or Category II non-friable ACM that has a high probability of becoming or has become crumbled, pulverized, or reduced to powder by the forces expected to act on the material in the course of demolition or renovation project operations.

Category I Non-Friable ACM: Asbestos-containing packings, gaskets, resilient floor coverings, or asphalt roofing products containing more than 1% asbestos as determined by using the method specified in 40 CFR Part 763, Subpart E, Appendix E, Section 1, Polarized Light Microscopy (PLM).

Category II Non-Friable ACM: Any material, excluding Category I non-friable ACM, containing more than 1% asbestos as determined by using the methods specified in 40 CFR Part 763, Subpart E, Appendix E, Section 1, Polarized Light Microscopy (PLM) that, when dry, cannot be crumbled, pulverized, or reduced to powder by hand pressure.

Locations found: Locations of building materials as described in this report indicate where they were found, but do not necessarily mean that these are the only locations where these materials may be encountered during the project.

Per EPA requirements, all materials analyzed as containing ≤10% asbestos are point counted utilizing EPA method 600/R-93/116 this information is summarized in Table 2.

Per Hill AFB requirements, all materials containing any detectable amount of asbestos shall be handled as Asbestos Containing Material (ACM). Table 2 shows the summary of materials containing ≤1% that were identified via "Point Counting". Per EPA/UDAQ ≤1% is not considered to be an asbestos containing material, but special handling/packaging requirements are necessary per OSHA 29CFR 1926.1101 and 29CFR 1910.1001

MATERIAL TYPE	ASBESTOS	QUANTITY	*LOCATIONS FOUND
N/A	N/A	N/A	N/A

Table 2.

The following is a list of the "Suspect Materials" that were sampled as part of this inspection:	
Stucco Wall, Tan	Thermal System Pipe Insulation, White Over Yellow
Thermal System Fitting Insulation, Brown	Thermal System Lagging Insulation, Silver Over White
Drywall Over Joint Compound Wall System	

Table 3.

A total of 14 samples reference the 5 suspect materials assessed as part of the inspection.

The following table summarizes the sampling data.

Homogenous Building Material, Description, Location, Quantity.	Sample #	Sample Location	Results
Stucco Wall, Tan, Exterior, 200 Square Feet	GM221802	Northwest	None-Detected
	GM221803	Northeast	None-Detected
	GM221804	North Center	None-Detected
Thermal System Pipe Insulation, White Over Yellow, Exterior, 300 Linear Feet	GM221805	Northwest	None-Detected
	GM221806	Northeast	None-Detected
	GM221807	Northeast	None-Detected
Thermal System Fitting Insulation, Brown, Exterior, 20 Linear Feet	GM221808	Northeast	None-Detected
	GM221809	Northeast	None-Detected
	GM221810	Northwest	None-Detected
Thermal System Lagging Insulation, Silver Over White, Exterior, 200 Linear Feet	GM221811	Northeast	None-Detected
	GM221812	Northeast	None-Detected
	GM221813	Northwest	None-Detected
Drywall Over Joint Compound Wall System, Electrical Room, 75 Square Feet	GM221814	East Center	None-Detected
	GM221815	Northeast	None-Detected

Table 4.

POTENTIAL FOR ADDITIONAL MATERIALS:

This inspection report only encompasses the areas/materials designated within the scope of work that was provided at the date of inspection (see title page for inspection date). Should the scope of the project be altered in any way or any materials found that are not identified in this report shall require additional assessment. This report cannot be used for any other projects within the building.

Any questions or concerns regarding this inspection report or if any new suspect asbestos containing material (ACM) is encountered, stop work and contact the personnel listed below for further assistance/assessment.

CONTACT INFORMATION

Asbestos/LBP Shop 75 CES(CEOHA)

Supervisor: Taylor Brimberry: DSN: (801)586-7094
Cell: (801)940-2970

Asbestos/LBP Shop Personnel
DSN:(801)777-8006



**DEPARTMENT OF THE AIR FORCE
75TH CIVIL ENGINEERING (CEOHA)
HILL AIR FORCE BASE, UTAH**



LIMITED NEGATIVE LEAD-BASED PAINT INSPECTION REPORT INFORMATION

SCOPE OF WORK: Install new chillers.

1-Positive Lead based paint readings were not-detected. Please refer to the final page of section of this inspection for all readings.

2-It is possible that lead based paint could be encountered during any renovation project. Additional identification for lead based paint on other building components may be required. The facility manager/Project Manager should ensure that these components are surveyed for lead as well, to meet OSHA Standard 29 CFR 1926.62 construction requirements for lead.

3-The U.S. Department of Housing and Urban Development defines Lead-based paint as any paint, varnish, stain, or other applied coating that has 1 mg/cm² as measured by an X-ray Fluorescence (XRF) Analyzer or by laboratory analysis of 0.5 percent by weight (5,000 µg/g dry weight) or more of lead. All other components tested were less than 1 mg/cm².

XRF Analyzer Used : XRF Analyzer XL3t 300 (Serial #96588)

4-Any effort to disturb lead paint can create lead dust. Ensure that appropriate abatement, cleanup, and disposal will be accomplished and that appropriate safety measures are taken IAW 29 CFR 1926.62. If you have any questions please feel free to call Taylor Brimberry at 586-7094.

5-This inspection report only encompasses the areas/materials designated within the scope of work provided at the date of inspection (see title page for inspection date). This report must be modified should the scope of the project be altered in any way or additional materials not previously identified within this report are encountered. This report may not be used for any other projects within the building.

Pre Calibration	PbL (mg/cm²)	Calibration Range
1408	1.01	Per 20 Second Reading
1409	1.16	
1410	1.06	
Range:	.8 to 1.2	

Model#	Serial #
XRF Analyzer XL3t 300 (Serial #96588)	

Post Calibration	PbL (mg/cm²)	Calibration Range
1413	0.96	Per 20 Second Reading
1414	0.86	
1415	1.15	
Range:	.8 to 1.2	

XL Number	Room/Area	Side	Structure	Paint Condition	Substrate	Color	PbL(mg/cm2)	NEG/POS
1411	Electrical Room	North	Wall	Good	Drywall	White	0.01	NEG
1412	Exterior	East	Edge Cap	Good	Stucco	Tan	0.01	NEG