APPENDIX 02

Photos of Existing Building


CAUTION
RADIATION AREA
DANGER


CAUTION
RADIATION AREA


DANGER
X-RAY IN OPERATION WHEN LIGHT IS ON
Bay
4
DANGER
c Computer
Lane


Bay 7
Bay 8


CAUTION
RADIATION AREA
809 MXSS
Radiographic Computer
Tomography
6321 Lemon Lane
Bay
4


CAUTION
RADIATION AREA
DANGER


SPEEDAIRE


SPEEDAIRE


SPEEDAIRE




CAUTION
RADIATION AREA
DANGER
RADIATION AREA



BEAM LIMIT 2000 LBS.
HOIST LIMIT 2000 LBS.

X-RAY ON
WHEN LIT

EXIT


X-RAY ON
WHEN LIT
BEAM LIMIT 2000 LBS
HOIST LIMIT 2000 LBS


R00445


STEAM




DANGER






120/208VAC
4A
WARNING
FRIEDRICH


440 V 60 CY
3 PH
A-1




ALARM
LIFT
&
PULL
SIEMENS











FUJIFILM
IX 100






B-5
B&J
15
DANGER


440 V 60 CY
3 PH


Bay
13




EXIT


FIRE ALARM
LIFT
&
PULL
A2
A3


EXIT
KODAK
INSTRUCTIONS (1 OF 2)


NOT AN EXIT
6
8
MXDVAAA






2113


2113
2113



Bay 15

Bay 16


Bay
13
Bay
14



Bay
11


Bay
12


CAUTION
RADIATION AREA
DANGER
809 MXSS
Radiographic Computer
Tomography
6321 Lemon Lane
















2113 2113
Bay 1
Bay 1




CAUTION
RADIATION AREA
DANGER

CAUTION


CAUTION
RADIATION AREA
DANGER
RADIATION AREA
CAUTION
RADIATION
AREA
DANGER


BEAM LIMIT 2000 LBS.
HOIST LIMIT 2000 LBS.
X-RAY ON
WHEN LIT
EXIT


CAUTION
HIGH RADIATION
AREA
CONTROLLED POWER COMPANY

STEAM

X-RAY ON
WHEN LIT

REMEMBER

FIRE

SG-TP21

SG-TP22


BEAM LIMIT 2000 LBS
DIST LIMIT 2000 LBS
1 TON
EXIT


SIEMENS
MXL


MAIN DRAIN
Gem


V-440


MAIN DRAIN
Gem
DELTA




SIEMENS
PAD-3
PAD-3
MXL




R00445


NO SMOKING


NO SMOKING
shop-vac
CONTRACTOR


FIRE
Hill AFB,
Utah
TECHLITES
Regular


984
777-1609
985
777-2800


Jessica LOTO 7.30.20 2.10.20
Jessica Fall Protect. 2.28.20
FIRE
FIRST AID KIT
CLOROX




013350
190#
TARE WEIGHT
100
Kodak








EXIT
Kodak
Kodak




Bay
13
Bay
14


EXIT
AMPEX

Bay

15

Bay
14


Bay
13
Bay
14


NOT AN EXIT
6
8
WERNER
WERNER


2113
T-2113
CA-16
351-375


2113
2113

2113

MAIN B
120/208VAC

LEAVE STEAM PIT

MAIN
B

LIGHTING

200-A

MAIN A-1
277/480VAC 3PH

MAIN
440-V

Main A-2
277/480VAC 3PH

MAIN
440-V

B-1
220-V

HEAT

B-2
220-V
3 PH

220-V
3 PH

2113

Bay
16

MAIN A-3
277/480VAC 0C
MAIN
440-V
3 PH 60 CY
A-3
200 A
CROUSE-HINDS CO.
SYRACUSE, N.Y., U.S.A.
ENCLOSED SWITCH CONDULET
WEATHER PROOF
CAT. NO. WMK 20035-1-77
3 WIRE 3 POLE 200 AMPS.
STANDARD H.P. RATINGS
VOLTS D.C. 600 A.C.
H.P. D.C. 50 A.C.
MAX. H.P. RATINGS
VOLTS D.C. A.C.
H.P. D.C. A.C.
KRSM 538461
RPIE
IS IN OFF POSITION.
MADE IN U.S.A.

2113

MAIN B
120/208VAC

200-A

LEAVE IN STEAM PIT

MAIN

B

OMNI-PHASE OSW

225 AMP 3 PH.

MAIN A-1
277/480VAC 3PH

MAIN

440-V

TRIPPED

OFF

RESET

NOTICE
TO RESTORE SERVICE
FORCE HANDLE TO EXTREME
OFF THEN THROW ON

225 AMP 3 PH.

Main A-2
277/480VAC 3PH

MAIN

440-V

TRIPPED

OFF

RESET

NOTICE
TO RESTORE SERVICE
FORCE HANDLE TO EXTREME
OFF THEN THROW ON

3 PH

B-1

120/208VAC

220-V

ON

TRIPPED

OFF

RESET

OMNI-PHASE OSW

SURGE PROTECTION DEVICE


Bay
16
2113


440 V 60 CY
3 PH
A-1
Friedrich
Bay
13

208 V
200 A
60 CY
3 PH
B - 1
B - 6


277/480VAC
A1-1
150 A
SPARE
277/480VAC
Bay
9


440 V 60 CY
3 PH
A-1
FRIEDRICH


Bay
9
FRIEDRICH
X-Ray And
Computed Tom
Office MADLND

DANGER
X-RAY IN OPERATION WHEN LIGHT IS ON

CAUTION
RADIATION AREA

Bay 5

Bay 4

3 PH


Westinghouse
A.C. VOLTS
600
DE-ION
CIRCUIT
BREAKER
TYPE
AB-1
POLES
3
NEUTRAL
AMPS.
250
3 PH
277/480VAC
CY
TRIPPED
OFF
RESET
150 A
NOTICE
TO RESTORE SERVICE
FORCE HANDLE TO EXTREME
OFF THEN THROW ON
SPARE